

VLS 500 And OBDII Issues:

The Following Issues Have Been Reported With The VLS500:

Manufacturer:	Model:	Year:	Issue:	Comment:
BMW	5 series, 7 series	All	OBD location, occasionally misses ignition OFF	
Chevrolet	2500	2004, 05, 07-08	Completely Incompatible	
Chevrolet	1500 Van	2004	Completely Incompatible	
Chevrolet	Silverado	1999, 2004, 2001	Completely Incompatible	
Dodge	Stratus	2001	Periodically read excessive speeding	
Dodge	Caravan	2001	Completely Incompatible	
Ford	Explorer	All up to 2000	Occasionally missed reading speed	Problem With OBD Protocol
Ford	Ranger	98	Occasionally missed reading speed	Problem With OBD Protocol
Ford	Escort	98	Occasionally missed reading speed	Problem With OBD Protocol
Ford	F250/350 Diesel	2001-2004, 2007	Stalled Engine	Problem With OBD Protocol
Ford	LCF	All	Completely Incompatible	
Ford	F650	2007	Completely Incompatible	
GMC	Cadillac STS	2005 and newer	Stalled Engine	unable to confirm, 1 incident
GMC	Sierra 1500	2000	Completely Incompatible	
GMC	2500		Completely Incompatible	
Isuzu	All Box Trucks		Completely Incompatible	
Jeep	Liberty	2005	Completely Incompatible	
Range	Rover	All	Completely Incompatible	
Saturn	L-300	2003	Completely Incompatible	
Unconfirmed				
Chrysler	PT Cruiser	2008	Cannot read ignition on/off	

Updated 01.06.2010